

CITY OF SIOUX CITY  
FIELD SERVICES-UTILITIES  
1921 18<sup>TH</sup> ST, SIOUX CITY, IA 51105

**SSO REPORT**

X PUBLIC        PRIVATE

LOCATION OF INCIDENT: 217 Woodland Way

REPORTED BY: Alex Zimmerman DATE: 2-4-19 TIME: 4 pm

SENT TO (IDNR STAFF NAME): Tom Roos (EMAIL, PHONE, FAX)

SSO START DATE: 2-4-19 SSO START TIME: 9:37 AM

SSO STOP DATE: 2-4-19 SSO STOP TIME: 1 pm

ESTIMATED VOLUME (IN GALLONS): 9158.52

CONTENTS OF SSO: Sewage

REASON FOR SSO: main blockage - goose

DID THE SSO REACH THE STORM SYSTEM: NO

IF YES, LOCATION OF OUTLET (NAME OF WATERBODY): N/A

DISTANCE TRAVELED ON SURFACE: Basement Footprint

DISTANCE TRAVELED IN STORM SYSTEM TO OUTLET: N/A

ACTION TAKEN TO STOP SSO: cleared blockage

PLANNED ACTION TO PREVENT FUTURE SSO (IF POSSIBLE): Added to  
monthly Test list, weekly monitor for next month.  
Televised line last year, no issues, brand new line.

SAMPLING REQUIRED: NO LOCATION OF SAMPLES: N/A

ADDITIONAL COMMENTS: Jayz Contracted to handle  
cleanup.

CITY OF SIOUX CITY, IOWA

UTILITIES DIVISION – SEWER SERVICE REPORT

☒ MAIN BACKUP ☐ PRIVATE SERVICE BACKUP ☐ SEWER GAS

1. Complaint Address 217 WOODLAND WAY  
(House or Building Address)

2. Did an SSO occur YES (If yes complete an SSO Report)

3. Received – Date 2-4-19 Time 9:23 AM

4. Arrived at Place – Date 2-4-19 Time 9:37 AM

5. Depth of Sewage in Basement 1.5' per Jay's Restoration-AZ

6. Caused by City Main YES

7. Caused by Private Sewer Service NO

8. Location of Plug (if main) 10 FT W. OF STONE PARK BLVD & CLIFTON

9. Cause of Plug GREASE

10. Apparent Damage: (Furnace) (Water Heater) (Washer) (Dryer) (Other)

Contents: Contact Don Trone AR 712-279-6320

11. Was Basement Cleaned by City Crews? NO

12. Were Occupants Satisfied? YES

13. Additional Information CHECKED M.H.'S IN BACK YARD OF  
3228 LINDENWOOD AND IN RADIUS OF STONE PARK BLVD  
& W. CLIFTON. BOTH WERE HOLDING WATER. JETTED  
MAIN FROM 321 CLIFTON TO STONE PARK BLVD. 300 FT  
TO OPEN MAIN.

14. Reported by D. TAYLOR Title MAINT.

Date 2-4-19